

301 East 69th Street / 1322 Second Avenue

Residential Building Complex | 2016

**CLIENT**

Judlau Contracting, Inc

LOCATION

301 East 69th Street / 1322
Second Avenue, New York,
NY 10021, United States

INDUSTRY

Transportation / Real
Estate and Insurance

SERVICE

Structural Dynamic
Analysis; Continuous
Monitoring

IMPACT

Documented stable tilt and modest changes in building response through project closeout.

CHALLENGE

Two neighboring buildings required monitoring during construction and load-transfer work for the Second Avenue Subway station entrance.

STRAAM APPROACH

STRAAM monitored 301 East 69th Street and 1322 Second Avenue and issued a final report, #31, confirming sensor removal.

RESULT

Tilt remained stable and the buildings' response changed modestly, giving the team a closeout reference.